11-30-11 WED 25/45 SUNNY 6:00/4:30 60
ROCHER - 1 SUPERVISION
DHM - 1 - AIR LINES
ANDERSON-ROT - 4 PUMPING WELLS
WELLS - 2 FABRICATE FRAMES FOR MCB
GOODMAN - COMPLETE AIR RELIEF, SAND BF #13 & PLACE 3" ON PAD
CAHOY (3) - COMPLETE WELL ROT #14, UNLOAD INNER CASINGS FOR NEXT 6 WELLS, ORGANIZE LAYDOWN SITE RU TO CHATHAM (TRACTOR TO T BRACE @ NEW CITY)

12-1-11 THURS 31/48 6:00/4:30 45
ROCHER (3) CLEANUP, HAUL & SPREAD ROCK ON LOT.
ANDERSON (4) EFFLUENT LAGOON PS.
ANDERSON WELLS (2) - FAB FRAMES FOR TUSS
DHM - AIR LINES
CAHOY: GROUT WELLS - CORK CASING BOTTOM WONT FIT.

12-2-11 FRI 32/50 6:00/4:30 45
DHM - 1 AIRLINES
CAHOY - WENT HOME IN A.M.
RU GT FORKLIFT TO REMOVE HEADER & FASTEN GROUTING
(2) ANDERSON & RU SET PLC FROM ROT

12-5-11 MON 6:00/4:30 33-41 45
(2) ROCHER - CLEAN & SEAL FLOORS, ROCK LOT
(1) DHM - MISC CONTROLS, CONNECT WELL #13
(4) ANDERSON - ROT - PULL WIRE
(2) WELLS - #13 GEAR, GND FIELD #10
(3) GOODMAN - VAULTS ON #10, SAND BF, STONE ON W 1/2 #10
(2) CAHOY - DRILLED P.M. - SET UP #9

12-6-11 TUES 6:00/4:30 28/35 45
LITERATURE
(3) ROCHER - CLEAN & SEAL FLOORS, ROCK
DHM - MISC CAPPING, CONNECT WELL #14
(4) ANDERSON - PULL WIRE, WORK W AAC
(2) ANDERSON - GEAR #13,
GOODMAN - VAULTS ON #14, SITE PIPE #10
CAHOY - PUMPS & PITLESS #9 (AX)
GROUTING #9
(2) AAC - WORK IN PLC-1
MASTER CLAVOR

12-7-11 WED 6:00/4:30 28/45 45
ROCHER - CLEAN & SEAL FLOOR & JOINTS.
(1) DHM - MISC PIPING
(4) ANDERSON - ROT - MISC. GEARING #13
(2) ANDERSON WELLS GND FIELD #14 & #9,
GOODMAN - VAULTS ON #9
CAHOY - LADDER ON #13, #10 PUMP
RU TO GREEN & BOOSTER & IMCO (G & B MANHOLE BASEMENT SUMP & REMOVE)
RECEIVED 4 WELL PANELS

12-8-11 Thurs 6:00/4:30 26/30 45

(3) Rocker: Clean Floors & Joints - Grade Rock: Install Latrooms From Soakaway

(2) ART's Install Tel Line

(1) DHM: Brine Piping

Anderson -

Goodman - (3) Site Poles #9 & #14

Conoy - Complete #9 pump install Install Grate & Hatch d/o.

12-9-11 Fri 6:00/4:30 60

(1) DHM - Brine Piping

(2) Anderson - Well #13

Goodman - Clear Debris From #1, Rock Base #11 & #1 (Extend)

Jerry Kuhn From IEPA & Accep. Tolled Plant & Well Field (2:30/3:30)

12-12-11 Mon 6:00/4:30 45

(1) DHM - Brine

(4) Rocker - Clean Floors, Lagoon Roadways

(4) Anderson - Tank Floats

(2) Anderson - Well #13

(3) Conoy Lute - Set up For Well #4

Goodman - Finish Rock approaches Trench Drainage @ RR ROW.

			ACT
Well #2 BM	GE	534.20	534.72
	FS	5.49	Corrected
	HI	539.69	
Pole Xsfer	MK	4.15 =	539.69
Down 1.69		1.69	
MK Pole		2.46 =	538.00
Set #2	FS	4.80	
	HI	539.00	
	BS.	4.82	
Mid Field	G.E	534.18	
	FS.	4.84	
	HI	539.02	
	BS. Well #1	5.27	Corrected
	G.E	53375	534.27
Pole Xsfer		4.75 =	539.02
Down		1.02	
MK Pole		3.73 =	538.0
Chk w orig #1			
Shot Pole		4.63 =	538.90
New HI		538.90	
Old #1		4.70	
		534.20	
Tie in back to BM		Pole #1	538.00
		FS	2.69
	Top	HI	540.69
535.86	Culvert		5.35
(See Next Page)		Error .5	535.34

WELL #3 XSFER

WELL #3	534.80	
FS	4.93	
HI	539.73	
POLE XSFER	3.57	= 539.73
DOWN	1.73	
	1.84	= 538.00

ERROR IS IN XSFER FROM BM 5586 TO WELL #2.

CORRECTION: FROM PAGE 131

ON TIE IN ACTUAL HI IS 541.21

THIS WILL RAISE WELL #2 BY .52 AND RAISE BOTH POLE BMS ON #1 & #2 LIKEWISE

INSTRUMENT CHECK 12-9-11 GST BERGER

ACCIMATE TEMP



ADJUSTED TILLE READ 3.28 Δ 1.18

1.18

6

WELL # 4 535.24

FS	4.69	
H.I.	539.93	
XSFER TO POLE		
DOWN	1.93	= 538.00

WELL #11 534.45

FS	4.70	
HI	539.15	
XSFER POLE	4.43	= 539.15
DOWN	1.15	
	3.28	= 538.00

12-13-11 TUES 6:00/4:30 32-38 45

(4) ROCHELLE — LOGAN ROADWORK, HOUR IN ROCK; GRADING @ SEPTIC AREA.
ANDERSON - GEN CLEANUP, TANK FLOATS
DHM - BRINE PIPING
GOODMAN - GREASE LEACH & RR ROW
CAHOY - TEMP WELL #4 FORCED — DRILL #11, SET SCREEN & CASING (STAYED UNTIL 2:30 A.M)

EPA MTNG

EPA TOUR

CH J3078 DO 21

Rainy (.75")

134

12-14-11 Wed 6:00/4:30 40-53 45

(3) Rocker - Clean Floors, Goose Lot

(4) Anderson

(2) Anderson - Well #13 almost complete

DHM - Pneumatic controls

(8) Canoy / Reynolds - Grout Well #11, Drill, set screen & casing #1 (52')

Goodman - O Wind 53-43

12-15-11 Thurs 6:00/4:30 45

(3) Rocker - Clean, Sea Floors, Grade Soil Pack - Start Pump in Det Tank

Anderson - Gen Grounding, Heat Trace, Tank Levels

(2) Anderson - Trim out Well #13, Chatham Heated Xs Fence,

Canoy - Grout Well #1, drill case & screen

Well #2 Secure Mount #4

DHM - Pneumatic controls, Test Ports

12-16-11 Fri 6:00/4:30 30

DHM - Pneumatics - Pump to Det Tank.

Anderson (2) - Complete Well #13, set PLC on #9 (R.V.)

(4) Canoy - Grout Well #2, started Gen Pump #1 (49' Deep To Grd)

135

Muddy

12-17-11 Sat 7:00/11:00 30

Canoy - Pump Test #1 started 10:30

Talked to Corey Several Times

during Step Test - All Good

375 GPM 9.5' Static,

23.3' at Pumping 6

Next Step Test: 2 Min Interval / 10 Min

5 Min " / 20

10 Min " / 30

30 Min " / Hour

Every Hour After

12-18-11 Sun 8:00/10:00 30

Moved BC cases in & set up

(3) Canoy - Moved Support Wells from #A to #3 & #5, Determin That #4 Is Not Practical Point

12-19-11 Mon 6:00/5:30 45

Rocker: Start Lagoon Empt

Pumps - Factory OK (ABS)

TVSS OK. (Set Final)

DHM - Automatics

Anderson: #9

Canoy / Reynolds - Loaded #9

Drill & Set Screen #3

Start Up #13 with AAC & TVSS

2:40 - 300 GPM Till 4:40

(37,500 G) - Took Bact Samp @ Pit

12-20-11 Tues 6:00/4:30 RAIN 35/45 60
SSWG MTNG
ROCHER; CLEAN & SEAL FLOORS
ANDERSON;
DHM
CAHOY: DRIVE & SET SCREEN #5,
12-21-11 Wed 6:00/4:30 38-45 45
ROCHER - CLEAN & SEAL FLOORS
ANDERSON (4)
ANDERSON (2) WELL #9
DHM - WATER LINES (W-1)
RV & TIM TOOK SAMPLES @ WELL & HYDRANT #2
CAHOY - WENT HOME
12-22-11 THURS 6:00/4:30 38-48 45
ROCHER - CLEAN & SEAL FLOORS, VALVES
DHM - W-1 LINES TO CLEAN ROOMS
(2) ANDERSON - PULL WIRE, CLEAN UP &
HAUL EXCESS MATERIALS
CAHOY - O
RV. SET QUICK CONNECT WELL #13,
STARTED WELL #13 & TOOK SAMPLES
H2O #2 & WELL
12-23-11 FRI 6:00/2:00 N.L. 33/43 30
ANDERSON (2) WELL #9
RV. QUIC CONNECT #9, OFFICE WORK
BACT OK TO H2O #3 per TIM

12-26-11 MON 10:00/4:30 32/45 30
ANDERSON - 2 WELL #9 PIPING
R.V. QUICK CONNECTS ON #10 & #14
12-27-11 TUES 6:00/4:30 45
RON TODAY - PUSH WATER FROM H2O
#3 TO RONT

20" TO LEACH CORNER	1823'
ANGLE ROCK	110'
RON ROAD SECT	524'
TO RONT	783'
TO PI EAST	220'
TO PI SOUTH	160'
TO PI EAST	415'
TO PI SOUTH	150'
TO AERATOR RISER	33'
RISERS ELEVATED & DOWN	40'
CROSS	13'
DET TANK & UP	27'
.81 MILE	4298'

CROSS SECT AREA 20" = 2.16 SF
= 9301 CF
(LRG CROSS = 650 GPM = 2½ MIN) x 7.5 = 69,760 G / 250 GPM = 4 HR 40 MIN - 2.5
CYL REQ @ 1.83 G/SF/C @ 1% = 3.95 4 HR 37.5 MIN
4800/100 = 43 x 3.95 = 169.85 / 12.5 = 13.6 G
/ 15 = 11.33
DISCONTINUE TODAYS RUN - IN ORDER TO GET SAMPLE, NEED POSITIVE PRESSURE ON TAP

DISCUSSED W/ TIM WE WILL CUT IN A CORP STOP W/ SADDLE ON RW RISER BEFORE VALVES, DELAY UNTIL POSS THURSDAY

(2) ROCHESTER - CLEAN & SEAL FLOORS
N.E. CORNER
OHM - O -
ANDERSON: PULL WIRE, FIRE ALARM
(2) DNC WELL #9 12-28-11 WED. 6:00/4:30 30/38 60
JULY'S PAVING @ G & R W TERRY
ROCHESTER: CLEAN & SEAL FLOORS
(2) ANDERSON PULL WIRE
OHM O
(2) ANDERSON WELL #9 & #13
(ANDY - O -
R.V. PUT A KWIK CONNECT IN VALVE VAULTS (2 LEFT)
12-29-11 THURS 6:00/4:30 37/52 45
(2 ROCHESTER CLEAN & SEAL FLOORS
(2 ANDERSON), PULL WIRE, FIRE ALARM
(2) ANDERSON, ANTENNA #13, TVSS #9 (R.V. WITH LUNCH)
QUENTIN W C.G. & R.V. SUCKLE DOWN HYD #3 FROM WELL 13 VV & ADDED 12 GAL CHL, AT 9:45 STARTED PUMPING MOVED TO #13. STORED COMING OUT DET TANK HATCH @ 2:20 - SHUT DOWN, ORDERED TOP SADDLE FROM IMCO

WELL #13 @ 9:45 45 HZ (75%)
PUMP ROSE TO START 273 GPM
11:15 PUMP ROSE 235 GPM
11:30 227 GPM
PUMPED UP VFD @ 12:10 TO 50.9 HZ (85%) INCREASED TO 277 GPM
1:30 269 GPM. DET TANK OUTFLOW @ 2:20
12-30-11 FRI 45/
(1) ROCHESTER SEAL FLOORS
12-30-11 FRI 6:00/4:30 DOWN 33/43 60
(1) ROCHESTER CLEAN & SEAL FLOORS
DEL, SHANE, & MEREDITH VISITED 1:30
AL MANUFACTURING DO
R.V. TO 3900, GET PUMP TO IMCO & TO CHEMTRON & BACK.
12-31-11 SAT 8:00/11:00 30
R.V. INSTALL LAG. 2 KWIK CONNECTS IN VAULTS, UNLOAD TOOLS & PAINT
1-2-12 MON 7:00/3:00 JULY WINDY 25/32 30
ANDERSON (4) FIRE ALARM
ANDERSON (2) WELL #9
R.V. PAPERWORK

1-3-12 Tues 5:00/4:30 4/33 30

Rocher (3) Exc ONO DR pod & H.C. Pkng Pod, Groge Form & Blanket. Exc & Install valve & 20' 6" pipe @ Tee To Water Soles Exc Around RW Risers For Heat Trace.

DHM - (- Install Valve & pipe - Misc W1 Piping

Anderson (4) - Fire Doors & Misc

Anderson (2) - Weld #10 conduit.

CG Tim & Quentin Shoot & Tap on RW - Wrong Tool Do Tomorrow

[redacted] showed @ 3:45 Unloaded Trucks

R.U. pumped Down Det Tank & swept muddy water

1-4-12 Wed 6:00/4:30 33/45 45

Rocher (3) Clean Floors, Groge Back Dirt & Lagoon Roads, Pwr wash Det Tank Floor.

DHM - W1 Lines in 100

Anderson - O at Plant (2) prefab for well #10

[redacted]: Set Well 10 Pump, Fasten Deck, Hatch & Ladder

CG (3) Tap RW Riser - RV Flush & Took Sample. Notify PM of Debris in Pits

PPH charged This dist Main with potable water ran To 60# & Then To 120#. Test Held. Air Release Worked & closed properly - Opened Curb Stops & Got Water. (AAC in PM 1 Guy)

1-5-12 Thurs 6:00/5:30 33/45 45

Rocher (3) Clean Floors, Groge Back dirt

DHM (1) W1 Lines Reset Level Tanks

Anderson (2)

[redacted] (2) Weld #10

Peoria Metro: Grind Cardbd off of sumps in Det & Overhead

AAC - Worked on Lagoon Ponds & PLC - (

[redacted] - Complete Well #14 Inc. setting Pump.

C.G - Turn Valves around in 6 vaults not installed

1-6-12 Fri 6:00/5:00 35/59 45

Rocher - Groge Dirt & Carpet Rock. Clean Floors, Layout Fence Chatham Blvd Locate UG For Fence

DHM - W1 Piping

R.U. - Drain MF1 & Det Tank To .42' Goodyear - Flush HVAC #2

ANDERSON (2) RC CAB'S REPOSET
LEVEL INDICATORS
[redacted] (2) WELL #10 CONDUIT
RV SET RC CABINET
AAC - LAGOON PANEL, TEMP DET
TANK LEVEL CONTROL
RV - PUMP & MOTOR DET TANK
FILL TO ± 7.5'

1-7-12 SAT 38/45 6:00/2:30 45

[redacted] (2) PUMP TEST #11 & SET UP #5 FOR FRACING

START @ 9:00 A.M. STATIC LEVEL 9.7'

TIME	PUMP LVL	DRAWDOWN	SPEC CAP
9:02	27.4	17.7	21.19
9:04	24.9	15.2	24.67
9:06	24.7	15.0	25.0
9:15	24.82	15.1	24.8
9:30	24.88	15.2	24.7
10:00	25.02	15.32	24.45
11:00	25.1	15.4	24.35
2:00	25.2	15.5	24.19
3:00	25.2	15.5	24.19

RECOVER TO 9.95 @ 3 MIN
PH-6.0 HARDNESS 427.5 MG/L

RV - TAKE PRESSURE OFF R.W & INJ 12 GAL OF NAOCL IN FLUSH HYD 3
DRAWBACK & OPEN VALVES - PUSH WATER FOR 4 HOURS TO REACH UPPER R.W. SYST. FILL DET TANK 10 12' ±
LAYOUT NEW WELL #4
FLUSH L.S. #3 10 MIN - CLEAR.

1-8-12 SUN 25/45 7:00/3:30 45

[redacted] (2) - PUMP TEST #5, AIRLIFT #3
RV, POWER WASH, LAYOUT WELL #4A 260' WEST OF PREVIOUS POS, SUPPLY WELL
ALSO - CHECK TANK LEVEL
[redacted] #5

SUN 11:00 STATIC LVL 9.65'

TIME	PUMP LVL	DRAWDOWN	SPEC CAPACITY
11:00	37.5	27.85	13.46
11:10	37.0	27.35	13.71
11:20	36.75	27.30	13.74
11:30	36.95	27.30	13.74
12:00	36.95	27.30	13.74 ↑
1:00	38.95	29.30	12.80
2:00	39.10	29.45	12.73 TRACE SAND
3:00	39.10	29.45	12.73
4:00	39.10	29.45	12.73
5:00	39.10	29.45	12.73 ↓

RECOVER TO 9.9' @ 5:08 PH 6.5 HARD 376.2 MG/L

1-9-12 MON 6:00/4:30 22/53 45

TANK LVL (DET TANK) IS 11.5' (ACTUAL)
ROMER: HAUL SPOILS TO CLAY PILE & WORK FIELD, CLEAN FLOORS, ADJ. DOORS
DHM (2) LAGOON OUTFALL PUMPS/PIPE
ANDERSON (2) HEAT TRACE R.W.
[redacted] (2) WELL #10
START L.S. PUMPS INC ALIGN - PURGE DIRTY MFI
ALIGN H.S. PUMPS

COLLINS & HERMAN (4) DRILL POSTS 144

[redacted] PUMP TEST #3

TIME		STATIC PMP LVL	LVL	9.55 O.D	SPEC CAP
	11:00				
11:02	375	37.5		27.95	13.42
11:06	285	36.8		27.25	10.46
11:10	285	36.9		27.35	10.42
11:30	252	33.6		24.05	10 48
12:00	252	33.36		23.81	10.58
2:00		32.84		23.29	10.89
5:00	252	32.68		23.15	10.89

RECOVER TO PH-6 9.8 IN 8 MIN 444.6 MG/L HARD

1-10-12 TUES 6:00/4:30 22/62 45

ROCHER (3) - DOORS, CAULK WALL JOINTS, LS PUMP PUMP DET WATER THRU FILTER INTO CREEK. PURGE S.E. & W1 LINE THRU FACE REPLACE (ISO)

(2) DHM LAGOON OUTLET

ANDERSON (2) SHOOT BOLTS, PICKET LITE

[redacted] (2) WELL #10

COLLINS-HERM (4) DRILL & SET POSTS

[redacted] TEST PUMP #2

375 GPM 11:00 STATIC 8.8

TIME	PUMP L.	DRAWN	SPEC CAP	SAND
11:02	35.5	26.7	14.04	
11:06	37.4	28.6	13.11	
11:15	37.54	28.74	13.05	
11:30	37.58	28.78	13.03	TOUCH
1:00	37.62	28.82	13.01	TOUCH
4:00	37.69	28.89	12.98	"
5:00	"	"	"	"

Heard Bunker Home

145

1-11-12 WED 6:00/4:30 32/45 45

ROCHER (4) - CLEAN UP OUTSIDE, PUMP MUDDY WATER FROM CLEARWELL, FLUSH SOFTENERS FROM TAP TO DRAIN OUTLET USING L.S. PUMPS & DETENTION WATER, BLOCKING FOR ANTENNAS, CAULKING, MAINT.

ANDERSON (2), HEAT TRACE, INSTALL ANTENNAS

[redacted] WELL #14

DHM - LAGOON OUTLET PUMPS, TIGHTEN FLANGES.

AAC (3) RC 1 - LAGOON PUMPS & MISC.

(5) COLLINS & HERMAN - COMPLETE POSTS

[redacted] WENT HOME

REYNOLDS - DRILL SUPPLY WELL #4 SNOWING / DN 22020

1-12-12 THURS 6:00/4:30 23/17 45

ROCHER (2) CLEAN CLEARWELL, PUMP TO LAG SUMP - FLUSH & DRAIN 4 SOFTENERS

DHM: MISC CHECK PIPING

ANDERSON (2) RC 1 TERMINATIONS

[redacted] (2) SET RC CAB #14

AAC (3) MISC RC WIRING, RADIO COM WITH #13, SECONDARY SET UP.

[redacted] - COMPLETE SUPPLY WELL #4 A. RV. HAS SAMPLES.

TIM, DOMERO, & R.V DISCUSS FLUSHING PROCEDURES.

AMCO - DRILL POST HOLES - 4 WELL SITES

1-13-12 Fri 6:00/4:30 = 17/9 30

(1) Rocher, Flush Ion Tanks, Add Water To Cur Well

(1) DHM - Ion Flushing, Clean Up

AMCO - Set 4 Four Fence Posts.

AAC - Complete Programming Det Tank & Lagoon Influent, Ferric Add com. w/ Well 13 & Process Remote Start/Stop

Reynolds pick up compass to send To Johnson Screens. Email From Collins Well #4A should be OK

1-14-12 Sat 3Hrs 60

To Plant 8:00 start ~~LS Pump~~ Well #13 Ran ~~Fill~~ 4.6' to 8.7' 9:00 to 1:15± 242 GPM Det Tank

Ran L.S. #1 8.7 to 6.7 900 GPM into Cur Wl. (2' added to Cur Wl)

1-15-12 Sun -4Hrs 60

To Plant 8:30 Meas Granular & Add To Det Tank @ 8:45/9:45 10.5# per Tank Flush Procedure. Left Well Running To Mix - Shut Down @ 7.8' & wait 30 min - Start Well #13 @ 10:40 @ 7.4' = 222 min To 11'-0" 3 Hrs 42 min = 2:22. Note - Well did not shut down @ 11'0 Manual Shut down 11.1'

1-16-12 Mon 6:00/4:30 40/60 30

Rocher (2) Gen Cleanup, Flushing, H.S. Pump Start, Drain Cur Well, by Good: Start: 1:00

DHM (2) - Chem Feed Piping, W/ Leaks Tim: Sample RW & MF1 @ Pump.

Collins - Hardware (5) Hardware attach cut off Posts

Anderson (2) Misc Wiring

Rocher (2) Well #14

1-17-12 Tues 4:00/4:30 48/31 75

Grout Drain from Cur Well 1:00 Do not stop until 5:05 AM.

RV early do watersched & start up sched.

RV To G&B for Cswlmtng, To Chatham, back To Plant

Rocher: (2) Drain down & start cleaning Cur Well, Drain down Det Tank, Insulate 20' 24 Standpipes

DHM (2) Chem Feed Lines

And (2) Aerator

And (2) Well #14

Canon (3) Excavate #1 RV Shot Grades @ 7:30 Collins (A)

BM 538.50
FS
HI 538.50
Well Cap 2.61
Elev. 535.89

1-18-12 Wed 6:00/4:30 12/25 45

Rocha (3) Groom backdirt & Rock
Clean Cuderhell, Wrap Tanks
DHM - Chem Feed Lines
Anderson: Aerator controls
[redacted] Well #14
Collins & Herron (5) Fence Fabric
& Detail
(4) [redacted] Well #1 Pipes, Exc Well
#2
Drain DT. Tank notice Iron on
bot, start Aerator & Put 1.5'
New Water in Tank
Cent Concrete - Layout Septic
To Cul Water Main at Wells
9,10, & 14
Main From #14

From AWWA for 1% solution

1124'-6"	11.25 x .36	4.05
910'-8"	9.1 x .65	5.92
976'-10"	9.76 x 1.02	9.96
		19.93

Say 20 gal / 15% solution
= 1.33 gal
For Gran @ 100% Cal = 1.66 #
Increase For 65% = 2.25 #
Add Handfull @

1-19-12 Thurs 6:00/4:30 30/25 45

R.V. & Damien determine that 4' of
Water Reqd for Tonka by:
9863 gal Fill
4750 gal B.W (475 gpm @ 10 min)
14,613
Run To Run up To 6' in Tank (±50%
start @ 1.8' need 4.2' = 210 min
= 3 Hrs 30 min. Start 7:10 AM.
Chlorinate To .5 MGL From Phase
III procedure 1.23# For Full Tank
Reduce x 50% = .62 # Added To
Tank @ 7:10
Reached 6' @ 11:02 Note: Increased Head
of 21' Had little effect on pump
performance (230 gpm)
Rocher (3) Clean Cuderhell with
Press. Cline, Groom Misc
Anderson: [redacted] - Misc Wiring
[redacted] (2) Complete Well #14
DHM - Chem Feed Lines
([redacted] Groom #11, Backfill #11
(Freeze Protect) & #2, Move Equip
To #11 & begin Excavation.
AAC: Set up Wells 9,10, & 14 Pump #14
Cent Concrete - Exc & Set 1,000 gal
Tank.
(2) Collins & Herron - Complete Fence

Run through Aerator

1-20-12 Fri 6:00/6:00 13/22 45
Rocher(1) > Flush & Disinfect Tonka (2)
DHM (1)
Gendron Cal(2) Set Pump & Elect Box
AAC(2) Programming (Wells)
PW Fill E-W 10" & 8" Main with High Chl Water
(4) Canoy Pitless on #11, Excavate #3
Dombek, Kerry & I attempted to Disinfect Softners 1 & 2. Followed Tonka procedures but could not get sample to feed post 8.8. Backflushed together @ 900 GPM for 25 min for complete flush.
1-21-12 Sat 8:00/3:00 cold 1.60
Started Well #13 @ 8:36 @ 3.4 D.T.
Added 2nd Chl to Tonk @ 10:15
Opened Flush Hyd #2, Added 3rd Granular to Well 14 & Ran 20 min @ 277 GPM. Note 2nd Grnl should raise Chl Level to 1 mgl but need 11' water. Water will use good portion of this.
Today Shutdown @ 1:45 SB 8' level
(4) Canoy Pitless on #3 Exc #5

Sun 1-22-12 10:00/2:00 32/40 60
Start Well #13 @ D.T. @ 8.2'
Shut off @ 1:30 @ 11'-0" No Luck on Pump Test #4
Canoy - Set Pitless Unit & backfill #5
Mon 1-23-12 6:00/6:30 40/34 45
Rocher (2): Clean up, charge syst for W-1 pressure > 5' water in Brine
(3) DHM: Domestic water, Chem Feed
(2) Anderson: Misc Wiring, Seismic restraint on lights
Canoy: Grout #1, 3, & 5 Add 20" casing & Bottom Tie #1
Brenmar Here for chemicals ordered Salt.
Don Held started Today —
Took Bacts @ 9, 10, & 14 & 10"
RW Main (Hyd #2). J-P Interview & WICS Live Feed
Westech came @ ± 2:30 - Tonka Tomorrow
Tues 1-24-12 6:00/4:30 30/38 45
Rocher (1) Work with Tonka & Westech
DHM (3) Chem Feed Piping
Anderson (2) Work with Tonka & Westech & AAC (1)
(3) Canoy Platform #1 & Grout

WESTECH (3) SYSTEM
TONKA (1) SYSTEM
BACT TO ALL WELLS & 10" MAIN
LEAK @ WELL #9 DUE TO STACK
P.E D.I. PIPE. TIM CONTACTED IMCO
RU's DON & TIM WORKED ON

1-25-12 WED 5:30/4:30 29/ 45
SOLT DELIVERY 6:00 A.M 25 TON N
SILO TIM DON RU REPAIR LEAK WELL #9
(1) ROCHER WORK WITH TONKA & WESTECH
(3) DHM - CHEM FEEDS
[redacted]
(1) AAC WORK WITH CONTROLS
BACT 9, 10, & HYDRANT & TONKA 3 & 4
IMCO WELL # 8 (NW) (3)

1-26-12 THURS 6:00/5:30 60
RU's PUMP & TO IMCO & ROCK WITH NEW CORP STOP. for STANDPIPE
RU & DON FLUSH for 1 HR - CHL STILL IN 10" LINE BACT 8 & 10 & HYD # 2
(1) ROCHER WORK WITH TONKA & WES
(3) DHM CHEM FEED LINES
(2) ANDERSON - WORK WITH CONTROL PEOPLE
AAC WORK W/ CONTROLS
WELL #9 IS APPROVED TO GO ONLINE
3:30 RE-CHLOR 10" & RUN WELL 8 2 MIN

Doors 3# Grav @ Well #14 rod

01-27-12 FRI 6:00/5:00 25/35 30
ROCHER: (1) - WESTECH & TONKA
DHM (1) - CHEM FEED
ANDERSON - MISC WIRING
AAC - CONTROL WORK
TONKA - RUN REGEN CYCLE & RINSE # 4
WESTECH - VARIOUS START-UP DUTIES
M&O INSPECTION (2) - INSPECT R.W & STANDPIPE.
TONKA NOTED THAT BYPASS LINE NEEDS TO BE REWORKED & LOOP INSTALLED TO PREVENT DEGRADING OF WESTECH
WESTECH NEEDS MINIMUM OF 2 2" AIR RELEASE VALVES INSTALLED WITH SURGE RESERVOIR.
NOTED TO TIM THAT IDPA NEEDS TO BE HERE WED OR THURS AM FOR INTEGRITY TESTING.
TIM & DON FLUSHED 10" LINE & BACT TO 8 & HYD # 2.
CHEMICALS DELIVERED - NO WAY TO UNLOAD FLOURIDE - LOADED FORKLIFT FROM SUBSET.

154

29/38

1-28-12 Sat. 8:00/4:00 30

Densified valve on #9. Added 3# Granular, Ran well for 10 min @307 GPM = 3070 GAL. Chl SB 180' West of Intersection. 800' to Hyd or 3,300 GAL. (13 min @ 250 GPM). Opened Hyd. Det Tank was @ 7.8' early. Started #13 (Well 7) @ approx 8:45 AM. At 10:30 added ½ # Granular to Tank. Add .5# to #8 after Dewat Sample Ran Then

Westech (2) worked on CIP skid, Located 10" valve @ lateral, worked with Westech on water supply issues - verify clearwell water elevation.

5.46 drop tape to water
15.92 to floor. 3848 SF
10.46 water level @ 28,783 G/LF
= 301,000 GAL
If BW, to 0 there will be 10,000 GAL left in floor slope.

33/38

1-29-12 Sun 7:30/10:30 30

9'-0" in Det Tank - Added .25# to comp
For loss & Fill 7'-0 to 11'-0. 10'-7½ meas
clr well = 15.92 − 10.62 = 5.3' = 152,550 GAL.
Westech (2) - Unpack & mount modules
Drain Clearwell

155

1-30-12 Mon 5:00/4:30 N.L. 30

Measured Clearwell - Drop Tape is 14.77 - 15.92 = 1.15 = 33,100 GAL to high spot. B.W. Pumps were pulling air so opened Hatch & put 2 submers in.

Brenntag delivered H2O2 Flood & bleach about 9:00

Discussed w/ Tim Potential Moth balling of Modules. Retrieved most Rigid Cops & Jumpers From Dumpster.

Rocker (1) - Pulsafeeder start up. Problem with Buscreed & Plumbing Connex. C.O. pending For Extras.

DHM (1) Chem Feed Piping
Anderson (2) Heat Trace Brine 2
(3) M&O: RW Lagging/Insulation
Tim & Don took Bacts on #8 #10, Hyd & #4.
Brooks & Assoc (2) work on Rack Feeders

35/45

1-31-12 Tues 6:00/5:00 40

Rocker (2) Cleaned, Drained & Piped Wash Clr Well
Anderson - Brine Tanks Heat Trace
AAC (1) - Controls
Start up Lagoon Effluent Pumps

29/35

2-6-12 MON 6:00/4'30 4 1/5

ROCHER: 1 - CLEAN UP

DHM: 1 - NEW AIR RELIEF CUT IN (LEAKER REPAIR) VALVE VAULT 0 # 5

ANDERSON: 2 CLEAN UP

ANDERSON: 0

CANOY - 0 (LATE PM ARRIVE)

GOODMAN (3) - VALVE VAULTS 0 # 5

ADJUST GRADES OTHER

DON & RV START HS PUMPS 3 & 4 RAN UP TO 59 HZ MAKING 115 PSI FLUSHED TO F.H.@ TRAILER (PPH) PPH OPENED ANOTHER VALVE PRES REDUCED TO 50 PSI. CLEWELL FROM 12.6 TO 6' IN 35 MIN +/-

BACTI NUMBER # 10 & > LAB

25/38

2-7-12 TUES 6:00/4:30 40

ROCHER: 2 CLEAN UP.

ANDERSON: 0

ROCHER PM - HONG TROLLEY BEAM HSP

DHM - CHEM FEED

(2) GOODMAN: COUPLER VAULTS 0 # 11, & # 05

CANO: (3) CUT CASINGS & SET UP FOR TOMMORROW DRILLING -

TAKE NEW BACTI ON N # 10

MICKEY BERNARD HERE FOR WESTECH FEEDERS

WESTECH - 2

CENTRAL - SEPTIC SYST.
M&O - (3) R.W. INSTALLATION
GOODMAN MOVE RIG
[redacted] (3) EQUIP PROBLEMS - SET CRATING
WELL #1
WESTECH: MAKE WATER TO CLEAN WELL
R.V. DRANK IT START WELL #9

2-1-12 WED 7:00/5:00 36/54 45
ROCHER (3) BACKFILL R.W. STRAPPERS
CLEAN UP.
(2) ANDERSON: HIGH CUT PUMP SITE
[redacted] GROUND IN WELL #1
DHM - AIR RELEASE C.O.
[redacted] WELL #2 CASING
GOODMAN - VALVE VAULTS WELL #1
AAC (PAUL) GEN CUTBACKS
CENTRAL (3) SEPTIC SYST.
START WELL #8 @ 11:00±
3 WELLS PUMPED 335,580 TODAY
TIM & DAN [redacted] .25" CL @ 7:30
@7.0 (
TIM & WESTECH FLOW: THURS PM. DISINFECT
CURVE @ LOW WATER, BACK ALL NIGHT
& ROSE TO OVERFLOW FRIDAY
TEST MON, TUES.

2-2-12 THUR 6:00/4:30 36/55 45
ROCHER (3) SPREAD ROCK, CLEAN UP,
COMPACT B.F.C. R.W./BERM
DHM: (1) MISC PIPING
ANDERSON (2) - CLEAN UP PUNCH ITEMS
AAC - 1 (GATE)
M&O - COMPLETE R.W. INSTALLATION
[redacted] - 3 - GRADE O-O #2, MOVE EQUIP
TO LAYDOWN
WESTECH (3) LEFT GEORGETOWN FOR
GOODMAN - COMPLETE VAULT WELL #1, INSTALL
VAULTS ON #2
CENTRAL: COMPLETE SEPTIC INSTALL

2-3-12 FRI 6:00/4:30 36/57 45
ROCHER: CLEAN UP, EXC SEPTIC
EJECT FEED.
ANDERSON (2) CELL PHONE ANTENNA,
SEPTIC HOOK UP
[redacted] (2) - GROUNDED WELL #1
[redacted] - O -
DHM 1 - VALVE VAULTS, CHECK FEED
GOODMAN (3) VALVE VAULTS, 2, 3, & 11 (CLAY)
.7 RAIN LAST NITE 30

2-4-12 SAT 7:30/11:30
CHECK PLANT / PAPERWORK / ADD 1# CAL
SILICATE TO #10 AFTER DRIVING VAULT TO
WELL. OPENED OUT VALVE & PUSHED MIX
TO WELL.

2-8-12 WED. 6:00/4:30 28/33 45

ROCHER(1) CO-ORD

DHM: CHEM FEED

ANDERSON: 2 - CELL PHONE DOP & MISC

WESTECH: 2 - MISC INC RC INSPECT.

COHOY: (3) - PREP FOR MOVE #5

PERIODS: DRILL #5: HAD TO QUIT DUE TO CAVING - #10 BACT GOOD

CITRIC DELIVERED

GOODMAN: 0-

2-9-12 THURS 6:00/4:30 25/40 45

ROCHER(1) CO-ORD

DHM(1) CHEM FEED, PORT WATER.

ANDERSON(2) SEPTIC TANK.

WESTECH: 2 SCADA & CHEM FEED

COHOY(3) PATTERN 0#11

GOODMAN(3) - TEMP PODS 0#3 & 0#11, ROCK PAD 0#5

START UP PULSA FEEDERS

PUMP FROM #10 BEELMAN 3" ± 4 LOADS

2-10-12 FRI 6:00/5:30 45

ROCHER(1) 2 HOLES

SET UP 2 FLUSHING HYD & PUMP CLR WELL DOWN FROM 11.82 TO 5' (96,300 GAL.) ADDED 11.5# GRAN TO CHL 18.225 G TO 50 MG/L

2-10 (CON'D)

COHOY(3) FINISH PATTERN & GROUT 0#11 - MOVE TO 0#3

GOODMAN (3) MOVE SPOIL TO #3 & #11 FILL LOCATIONS. LEVEL & BUILD PAD NEW #6.

BEELMAN DELIVERED 16 LOADS 3" -

TRUCK #1155 HIT POWER LINES ±10:30 NOTIFIED TERM MGR & CHOTHOUM (SHANE) FOR REPAIR. SHUT DOWN WELLS 10, 9, & 8 UNTIL REPAIR COMP. (±1:15) & RE-STORTED. TERM MGR MICK BUTLER INSPECTED SITE & CONFIRMED ACCIDENT.

DON & R.V. STORTED V.F. @ 1:20 CONED WESTECH WITH CONCERN OF AUTO B.W. WITH HI CHL WATER. DON EXTENDED CYC TO 90 MIN & SHUT DOWN @ 80 MIN TO CONFER. PERRY/CODY: CON B.W. WITH HI CHL WATER (NOT ADVISABLE). AFT BW BEFORE TO RUN FILTERS ± 10 MIN TO COMPLETELY RINSE HIGH CHL FROM MODULE.

17/22

2-11-12 SAT 9:00/2:00 (NL) 33

CRHAY(3) CASING & PLATFORM #4 0

R.V. CHOILS, TIME & EXPENSES, PUNCH OFFICES & CHEM ROOMS & MASONRY IN OPERATIONS. MAKE UP 2 EXPERIMENT HOSE HOLDS FOR WELLS. DRAFT CLEARWELL DOWN & FILL RENAMP.

2-12-12 SW 9:00/11:00 30

CRHOY: (3) N WELL #6 WELD CASING & SET PLATFORM.

2-13-12 MON 6:00/4:30 22/32 (LITE SNOW) 45

ROCHER > MASONRY & PREPARE PUNCH L.

ROCHER (2) CO-ORD. CUT OUT & PATCH BED JOINTS, CLEAN CHEM ROOMS

DHM(1) BLEND LINE CHEM CHK VALVES

ANDERSON(1) FENCE GROUND

AETNA(1) PAINT TROLLEY BEAMS

CRHOY (3) GRAIN MP #4, CASING & PLATFORM #6 NOTE ON A dust GOODMAN -O-

MET W G. KUNZMAN & D HEISENGER & SURVEY CREW RESUM ROAD LOCATIONS & TREE ID

ISSUED SKETCH TO ALL CONCERNING CLEARWELL FILL & DRAIN CHANGE

30/40

2-14-12 TUES 6:00/4:30 30

ROCHER (2) CO-ORD & CLEANUP.

DHM(1) REPUMP BLEND LINE, DRILL S.E. FOR CLOUDL, TAP MFI IN AT.

ANDERSON(1/2) - FENCE GROUNDING

DESIGN TANKS(1) BRINE START UP

AETNA (1) CUT IN WALLS TO FLOOR, MISC TOUCH UP.

M&O INSULATE DUCTWORK

CRHOY: SET PUMP N# 6, GROUT CASING. - CREWS LEFT MID MORNING

GREEN & BRADFORD (3) SURVEY ROADS

36/42

2-15-12 WED 6:00/4:30 30

ROCHER (1/2) - CLEAN UP, CO-ORD

AAC-(2) IN P.M. HIGH SPEED PUMPS PLC SCREENS

DHM(1) EARLY DRILL S.E. FOR GA-VAL

ANDERSON -O- & HOOK INTO SPRINKLER MAIN

STARTED U.F @ 8:14. DON OPERATED MANUAL & RAN BANK 1 & 2 & BACKFLUSHED. DISC BANK 3 HAD ALARM TO DO WITH VFD. AT 10:15 CORY TOLD DON HOW TO RE-SET ALARMS & GET SYST TO RUN

1'± WATER IN HIGH CHL. VAULT

SHUT UP HIGH CHL PUMPS

PUMP LAGOONS DOWN ±9"- PUMP #1 NOT RUNNING PROP

HEADLAND 1 - SPRINKLER MAIN

EAST SIDE - SPRINKLER MAIN

37/43
2-16-12 THUR 6:00/4:30 6 30

ROCHER: H.C.SON, PUMP DOWN LAGOONS, CLEANUP

DHM(1)-NEW CURWELL FILL, FIN FIRE MAIN

ANDERSON(1) COMPLETE GRADING

A.A.C. (2) ROAD COMPLEX W/CHOTHAM

GOODMAN (3) COMPLETE PADS. W/CA-6,

HEARTLAND (1): TEST FIRE SUPPRESSION SQUEEUR 200# PRESSURE: ROCHESTER DEP CHIEF.

35/45
2-17-12 FRI 6:00/4:30 40

ROCHER (2) LOAD OUT, CLEAN UP, CAULK JOINTS

ANDERSON (1) FIRE DOORS

ANDERSON (2) WELL PLATFORMS

DHM: (1) POTABLE, FLUSH HYDRANT & VALV, FRONT WATER LINE, WATER TO HEAD, SIMC IN BRK

GOODMAN: POTABLE HYDRANT, CA-6 BASE OVER 3" @ WELL SITES

2-18-12 SAT 8:00/10:00 30

WELL RUNNING (±4A)

28/40
2-20-12 MON 6:00/4:30 40

ROCHER (2) CLEAN & PREP WASH FLOORS

1 DHM: SINK & FAUCETS IN LAB

1 ANDERSON: CLEAN UP

M&O INSULATE ABOVE CHEM ROOMS

GOODMAN - GRADE AROUND PADS, TANK 9

ANDERSEN - BRACKETS & GRANNING 6

CDHOY - 2:00

FILL CURWELL W/CHOTHAM WATER & ADDED 1½ # GRANULAR

34/42
2-21-12 TUES 6:00/4:30 65

SSWC MTNG @ PLANT

ROCHER - CO-ORD

DHM - FAB PIPE STAND

ANDERSON - PREP FOR GEN START

RUN HSP# 5 FOR 2 HRS ± EARLY & MID

C1 DM - TAKE BACT TO LAB 12:00 NOTE CURWELL IS OVERFLOW - HIGH CHL

MOY W/TONKA: START UF SYST LATE PM. RUN CURWELL FROM 6.8 TO 9.5. DET TANK DOWN TO 6.6. NOTE WELLS did NOT START. ~~USED~~ AUTO

[redacted] WELLS N 10 & 9

?

2-22-12 WED 40°/55 6:00/6:00 N.L. 60°

WELLS did not restore on AUTO. Acknowledged Alarm & start well process to start. All 4 pumping Ave 244 GPM. Started at 6:17 AM. Rocker: Lag 2 & 2 Lag 1 dropped off At 7:45 - Lead dropped off @ 12.2' Start Hot 5 @ 9:45 cur well 10.7'. Ran most of Day.

Start up Gen/Xfer switch system. Issue with exercising Xfer R.F.I. To come. NOTE AC will not restart Rocker ½ CO-CRO: W/O manual Reset.

DHM: 1 work w/ Westech & Tonka

(3) Anderson: Work w/ Cummins / S&C

Chothom: 4 work w/ Cummins / S&C.

Problem with Westech providing press to Tonka. Discovered incomplete B.W. cycles due to lack of Air. Cook/Frank/Andy worked with until 7:30 P.M. Tonka got Re-Gen of #4. Took Bact to P.A. for C-2 (clear) @ 12'00±. Note good results for C-1.

AAC-(2) work with Tonka & Westech

Canon: 2 - Detail Well #8

Westech-1

Tonka-1

40°/57 459

2-23-12 THUR. 6:00/4:30

Start Det Tank @ 12.0 cur well @ 8.3. Andy noted Clavol will have to be mounted horiz. Also note that Andy indicated SI line will always drain to Cl well since S.E. line is at same elevation.

Flushed sumps out of Det Tank Lots of Mud/Iron

Befumon: 14 loads CA-6, 2 loads 3"-

15'-3" Brace to Floor 12'-6" brace to water = 2'-9" water in High Cl

Regen Ran late 2400 gal per Tank To High Cl !!

Rocker -0-

DHM-0

Canon-0

Anderson-1 As Builts

Chothom-2 Well #1

Goodman-1 Goode Roadways Inc

Leach + Push up Rock

Westech-1 Chem Feeds

Tonka-1: Regen

!